



Attachment 3-B Photographs of Groundwater Monitoring Wells












NRF-7 wide and close-up views.



NRF-7 close-up showing unsheathed wiring.




















NRF-13 wide and close-up views.

This Page Intentionally Left Blank.